Rolls-Royce

Rolls-Royce Corporation
T56-A-15LFE

COMMERCIAL SERVICE LETTER (CSL)

Technical Publications Index

April 1, 2014

Rolls-Royce

COMMERCIAL SERVICE LETTER INDEX

CSL No.	Subject	Published	Revised
1501	T56-A-15LFE Engine Life Limited Parts	Cancelled	Ref. CSL-1545
1502	Approved Lubricants - Engine Oil System	02-16-73	No. 8, 05-19-08
1503	Reduction Gear Starter Pad Drain Hole	02-15-74	
1504	External Scavenge Oil Filter - Description and Maintenance	05-07-74	No. 1, 08-15-01
1505	Foreign Direct Sales - Procedure To Obtain Technical Orders for T56-A-15LFE Engine	Cancelled	
1506	501-D22A, -D22C, and T56-A-15LFE Engine "Torching"	05-31-74	
1507	Authorized Engine Overhaul and Repair Centers	07-31-74	No. 27, 10-22-12
1508	Use of Wide Shroud Second Stage Turbine Blades	02-28-75	
1509	Engine Oil System - Cleaning	09-04-75	
1510	Engine Oil Loss	04-04-75	
1511	Use of Cup Washer Locking Devices On Reduction Gear Assembly Accessory Drives	01-23-76	
1512	501-D13, -D36, -D22, -D22A, -D22C, and T56-A-15LFE Engine Oil Leakage	02-13-76	No. 3, 02-02-78
1513	Engine/Propeller Control Linkage Inspection Engine and Propeller	03-05-76	
1514	Communications and Part Ordering Procedures	Cancelled	
1515	Use of Front Compressor Bearing Containing Corrosion Resistant Steel	12-23-77	
1516	Replacement of Fuel Hose Fire Sleeving	06-02-76	No. 1, 05-17-00
1517	Procurement of Publications	10-22-76	No. 4, 03-11-02
1518	Use of Manufactured Parts Not Sanctioned By DDA-606/606A Propeller and 501 Engines	Cancelled	
1519	Deletion of Internal Retaining Ring, 6842789 From Turbine Coupling Shaft	01-31-78	
1520	Inspection of Prop Shaft Thrust Nut Lock Installation On Power Plant Installations With Hamilton Standard Propellers	07-21-78	No. 1, 07-30-81
1521	Permanent Identification of Scrap Parts/Assemblies -606/-606A Propeller and T56/501 Series Engine	10-10-78	
1522	Magnetic Plugs 6792118, 6822092, and 6822222	01-29-79	
1523	Temp Datum Valve Motor Retaining Screw (Retorque)	02-06-79	No. 1, 11-21-80
1524	Fire Extinguisher Material (Cleaning)	08-30-79	No. 2, 02-27-80
1525	Compressor Inlet Blockage	08-15-79	No. 3, 02-03-99
1526	Engine Inspection Requirements When Exposed To Volcanic Ash	06-02-80	
1527	Unexplained Loss of Propeller Oil (Hamilton Standard Propeller Installation)	07-15-80	
1528	Oil Leakage - Accessory Drive Housing Fitting	02-12-81	No. 1, 02-28-91
1529	Use of Military Surplus and Unapproved Parts in Rolls-Royce Commercial Engines	07-10-75	No. 4, 05-10-01
1530	T56-A-15 and T56-A-15LFE Part Number Differences	10-15-81	No. 3, 12-15-91
1531	Turbine Vane To Spacer Rubbing	11-30-82	

CSL No.	Subject	Published	Revised
1532	Engine Performance - Maintenance Ground Check Procedure 501-D22A, 501-D22C, T56-A-14LFE, and T56-A-15LFE Engines	Cancelled	Ref. CSL-1561
1533	Allison T56LFE Engines - General Information	07-15-83	
1534	Cancelled Prior To Publication		
1535	Reduction Gear Prop Shaft Seal, 6851491	03-28-85	
1536	Propeller Retaining Nut Torque	06-15-86	No. 5, 06-30-08
1537	Identification of Allison Power Parts (APP)	08-15-85	
1538	Reduction Gear Propeller Shaft Seal Assembly, 6875798	02-26-86	
1539	Return Of Parts For Field Investigation At Allison Or Allison Approved Distributors Or Maintenance and Overhaul Centers	02-28-86	
1540	Scavenge Oil System Test Kit, 23037932 Availability	Cancelled	
1541	Cancelled Prior to Publication		
1542	Seal Shelf Life - Age Control	07-00-89	No. 1, 04-01-90
1543	Operation of Bendix Fuel Control and Power Turbine Governors Exposed to Fire or Severe Overtemperature	12-01-89	No. 1, 04-01-90
1544	Improved Anti-Icing Air Valve Seals	08-00-89	No. 1, 01-31-94
1545	T56/501D, Series II, III, Engine Life Limited Parts	12-10-65	No. 21, 07-18-11
1546	Reduction Gear Assembly Splitline Torque Procedure	02-28-91	
1547	Excessive Oil Consumption In-flight and/or on Ground	02-28-91	
1548	Replacement Battery for Temp Trim System Test Set 6799111 and 6799215	06-01-90	
1549	Scavenge Oil System Test Kit 23008696	03-31-93	No. 1, 04-15-93
1550	Cancelled Prior to Publication		
1551	Starting Procedures	03-15-93	No. 1, 09-01-95
1552	T56-501D Temp Datum Amplifier 23009257 Recall	06-28-95	
1553	Rolls-Royce Parts Ordering Process	06-28-95	No. 2, 03-11-02
1554	T56-7A/7B to T56-A-15LFE Conversion Kit Release	06-28-95	No. 2, 06-15-06
1555	Introduction of New Compressor 5th-and 10th-Stage Bleed Gaskets	07-06-95	
1556	Operation and Maintenance of the T56 Thermocouple	07-06-95	
1557	Turbine Module Installation Kit Release	07-24-95	No. 2, 12-01-97
A1558	Alert Severe Over-Temperature Operation	07-26-95	
1559	Power Section, RGB Oil Pressure Limitations	07-31-95	No. 1, 05-05-99
1560	Technical Manual Current Issue Status Report	Cancelled	
1561	Engine Performance Ground Check Procedure Performance Calculations and Trending Software and Support Equipment Release	11-29-96	No. 6, 01-30-14
1562	Fuel Nozzle Bolt Lubricant	09-25-95	
1563	Prop Shaft Cleaning at Installation	09-25-95	
1564	Engine Fuel Nozzle Cleaning	09-25-95	
1565	Paralleling Valve, Fault Isolation	09-29-95	
1566	Scavenge Oil System Test Kit, 23008696	10-09-95	

CSL No.	Subject	Published	Revised
1567	Disabling the Fuel Enrichment System	11-30-96	No. 1, 11-15-97
1568	Certification Status, Allison 501-D36 Engine	02-28-97	
1569	Improved Starting Fuel Schedule	12-01-97	No. 1, 01-26-98
1570	Updated Compressor Inlet Temperature (CIT) Correction Charts	01-26-98	No. 2, 10-23-06
1571	Compressor Inlet Sensing Probe Torque	11-15-97	
1572	Overboard Fuel Venting	12-01-97	
1573	T56/501D Series III 2nd-stage Wheel Measurement	12-15-97	
1574	T56/501D Series II and III Unexplained Oil Loss	05-20-98	
1575	Operation and Maintenance of T56/501D Engines in Erosive Environments	02-23-98	
1576	T56/501D Engine Overtorque	01-26-98	
1577	Allison T56-LFE Engine Information	11-15-97	
1578	Use of Low Speed Ground Idle	01-26-98	
1579	T56/501D Pinion Bearing Limits	01-12-98	
1580	T56 Engine Torching at High Power Settings	03-15-98	
1581	Titanium Nitride (TiN) Coated Compressor Blades	03-09-98	
1582	Allison Repaired Combustion Liner Exchange	02-03-99	
1583	Water Quality for Engine Wash/Rinse	01-28-99	
1584	Alternates For ODC/EPA-17 Chemicals	09-23-99	
1585	Alternate for Acti-Thane WC-100 Paint	04-05-00	
1586	New Spring for use in Fuel nozzle Assemblies	05-17-00	
1587	3 Micron External Scavenge Oil Filter	02-01-01	No. 1, 10-19-05
1588	Reduction Gearbox (RGB) - Main Drive Gear Bearing Failures	05-10-01	
1589	Warranty Policy GT-8545 (B) Dated 5/00	02-08-01	
1590	P/N 6847349 Turbine Inlet Case Machining Condition	06-25-01	No. 1, 06-28-01
1591	Shipment of Fuel System Components	10-25-01	
1592	Visual Color Change of 3rd-Stage Turbine Blade, P/N 6875243	12-03-01	
1593	Spare Part Warranty Return Process	02-01-02	
1594	P/N 6852412, 4th-Stage Turbine Blade	08-31-04	
1595	Thermocouple Assembly, P/N 23075403		No. 1, 05-26-05
1596	New 1st-Stage Turbine Blade P/N 23062421 Visual Differences From The Original P/N 23065975	07-12-05	
1597	Non-Destructive Testing (NDT) Requirements for Prop Control Intermediate Link Rod Assembly & Prop Control Rear Link Assembly	05-12-06	
1598	To Clean the Engine of Bird Residue After a Bird Strike	02-26-07	
1599	Inspection Required Following Metal Generating Failures	05-12-09	
1600	Use of Accident - Incident Hardware	03-07-11	
1602	Nose Scavenge Oil Pickup Tube at Reduction Gear Front Housing - Installation Issue	11-07-11	

CSL No.	Subject	Published	Revised
1603	Repair of 2nd-, 3rd-, and 4th-stage Turbine Vane Inner Diameters	05-23-11	
1604	Jet Fuel Contaminated with Fatty Acid Methyl Ester (FAME)	01-30-12	
1605	Loctite Plastic Gasket 568 (Loctite 68 or Loctite 56841) Replacement	08-20-12	